

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025



February 21, 2012

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

Mr. Steve Hepler Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 12-0045

ACHD Reference Number: 14500 Sulfur Plant Incinerator USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

James F. Dudek Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 12-0045 ACHD Reference Number: 14500

- 2. Date & Time of Breakdown: Date: 02/20/12 Time: 0930 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: Sulfur Plant Incinerator
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA

Nature and cause of breakdown: The sulfur plant spare incinerator B684 was unavailable for service while calibrations were performed on the thermal coupler. The sulfur plant incinerator B684 is a redundant piece of equipment and the 684A incinerator carried load.

- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The 684A incinerator carried the load. No environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted). No environmental impact
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 The 684A incinerator carried the load.
- 10. Facility back in operation Date: 02/21/12 Time: 1010 hours

Signature / Luch Davis Date 2-33-12

Senior Environmental Control Engineer Phone: 412-233-1015